

# TYPE "T" DIES 100 MM | MATRYCE TYPU „T” 100 MM

24h 42CrMo4

**M 7106** 100 t/m

A = 6 mm, B = 20 mm

24h 42CrMo4

**M 7108** 100 t/m

A = 8 mm, B = 20 mm

24h 42CrMo4

**M 7110** 100 t/m

A = 10 mm, B = 20 mm

24h 42CrMo4

**M 7112** 100 t/m

A = 12 mm, B = 25 mm

24h 42CrMo4

**M 7116** 100 t/m

A = 16 mm, B = 30 mm

24h 42CrMo4

**M 7120** 100 t/m

A = 20 mm, B = 30 mm

24h 42CrMo4

**M 7124** 100 t/m

A = 24 mm, B = 35 mm

24h 42CrMo4

**M 7130** 100 t/m

A = 30 mm, B = 45 mm

24h 42CrMo4


**M 7140** 100 t/m

A = 40 mm, B = 55 mm

24h 42CrMo4

**M 7150** 100 t/m

A = 50 mm, B = 75 mm



42CrMo4


**M 7260** 100 t/m

A = 60 mm, B = 75 mm

42CrMo4

**M 7280** 100 t/m

A = 80 mm, B = 100 mm



42CrMo4

**M 7306** 50 t/m

A = 6 mm, B = 20 mm

42CrMo4

**M 7308** 40 t/m

A = 8 mm, B = 20 mm

42CrMo4

**M 7310** 40 t/m

A = 10 mm, B = 20 mm

42CrMo4

**M 7312** 40 t/m

A = 12 mm, B = 25 mm

42CrMo4

**M 7316** 45 t/m

A = 16 mm, B = 30 mm

42CrMo4


**M 7320** 50 t/m

A = 20 mm, B = 35 mm

42CrMo4

**M 7324** 50 t/m

A = 24 mm, B = 40 mm



# TYPE "T" DIES 55 MM | MATRYCE TYPU „T” 55 MM

42CrMo4

**M 7406** 100 t/m

$\alpha = 90^\circ$

A = 6 mm, B = 15 mm

42CrMo4

**M 7408** 100 t/m

$\alpha = 90^\circ$

A = 8 mm, B = 15 mm

42CrMo4

**M 7410** 100 t/m

$\alpha = 90^\circ$

A = 10 mm, B = 20 mm

42CrMo4

**M 7412** 100 t/m

$\alpha = 88^\circ$

A = 12 mm, B = 20 mm

42CrMo4

**M 7416** 100 t/m

$\alpha = 88^\circ$

A = 16 mm, B = 30 mm

42CrMo4

**M 7420** 100 t/m

$\alpha = 88^\circ$

A = 20 mm, B = 30 mm

42CrMo4

**M 7424** 100 t/m

$\alpha = 88^\circ$

A = 24 mm, B = 40 mm

42CrMo4

**M 7432** 100 t/m

$\alpha = 85^\circ$


A = 32 mm, B = 50 mm

42CrMo4

**M 7440** 100 t/m

$\alpha = 85^\circ$

A = 40 mm, B = 55 mm



42CrMo4


**M 7540** 80 t/m

A = 40 mm, B = 55 mm, H = 55 mm

42CrMo4

**M 7560** 60 t/m

A = 60 mm, B = 80 mm, H = 65 mm



42CrMo4

**M 7606** 35 t/m

A = 6 mm, B = 15 mm

42CrMo4

**M 7608** 100 t/m

A = 8 mm, B = 15 mm

42CrMo4

**M 7610** 100 t/m

A = 10 mm, B = 15 mm

42CrMo4

**M 7612** 40 t/m

A = 12 mm, B = 20 mm

42CrMo4

**M 7616** 45 t/m

A = 16 mm, B = 30 mm, H = 55 mm

42CrMo4

**M 7620** 50 t/m

A = 20 mm, B = 35 mm, H = 55 mm

42CrMo4

**M 7624** 50 t/m

A = 24 mm, B = 40 mm, H = 55 mm

42CrMo4

**M 7632** 50 t/m

A = 32 mm, B = 60 mm, H = 60 mm

