

Operating mode

- The iControl load indicator measures the hydraulic pressure in a circuit.
- The measuring of the load is dynamic, i.e. constantly updated.
- The operator can add the current load to the accumulated total by pressing a key or not.
- The operator can retrieve the last load from the accumulation.
- The operator is warned by a buzzer and a message in case of overload.



WARNING! Please contact us if the cylinder is fitted with check valves.

Graphical version

- Fully tactile screen.
- Readable beyond 5 metres.
- Easy to use, sturdy box, self-explanatory program.
- Multi-site management.
- Multi-product management per site.
- Overload and product load threshold warnings.
- Ideal for trading transaction: $\pm 5\text{kg}$ accuracy (with optional position sensor only.)



Specifications

- With 0-5V DC / 0-250bar pressure sensor.
- Overload alarm and message indication.
- Step-by-step calibration.
- Data transfer using USB stick (for invoicing).

Contents

- 1 Hydroscreen screen.
- 0-250bar pressure sensor. Max. pressure: 750bar.
- 1 electric harness (power supply + sensor).
- 1 arm mount with suction pad.
- 1 pressure tapping of your choice.

Date and time


Actual net weight in kg

Selected site

Selected site info:

Total cumulated load and number of loadings.

Display the cumulated load per site.



Selected product

Display the current product and its cumulated weight.

Product selection keys